

## Machine Operation

## Use safe practices while operating machines.

- Inspect machines before use.
- Do not perform maintenance unless authorized.
- Lock out and tag machines off before performing maintenance.
- Scan for sharp edges, pinch points and hot surfaces.
- Avoid wearing loose clothing.
- Never bypass safety switches, guards or shields.
- Wear eye protection when exposed to flying objects.

## For more information:



